

Following is a correction to the recommended land pattern in the databook:


- Radio-Frequency Semiconductors Diodes
- Document ID: BDE0003D
- Published in 2006-9

P. 112

Wrong:

SMQ package


(16) SMQ



Right:

SMQ package

(16) SMQ



The updated version of the databook is posted on the Toshiba Semiconductor website at:  
<http://www.semicon.toshiba.co.jp/eng/>