

Following is a correction to the recommended land pattern in the databook:


- High-Frequency Semiconductors Power Devices
- Document ID: BDE0022B
- Published in 2004-3

P. 100

Wrong:

SMQ package


- (6) 4-Pin super-mini package (SMQ)
(JEITA: SC-61B)



Right:

SMQ package

- (6) 4-Pin super-mini package (SMQ)
(JEITA: SC-61B)



The updated version of the databook is posted on the Toshiba Semiconductor website at:
<http://www.semicon.toshiba.co.jp/eng/>